





PLT-SUPPL-0046



We cannot locate the leak. It's under the surface. No bubbles. No nothing. I've looked every fkn where

And tried everything

Brent L.

Unbelievable

Feb 26, 2021 at 1:06 AM



PLT-SUPPL-0045

Leeeeeee

I mean what we looking at

Feb 26, 2021 at 2:34 PM

We put the boat back into the water and we don't see any significant leaks.

Ran thru the entire boat.

We do see some sort of backfired from the bilge pumps which Eric saw and he is going to look into

Back feed. Not backfired*

Brent L.

B Weird

Leeeeeee

Ok

We have no power and things are malfunctioning due to the water ingestion.

PLT-SUPPL-0044

We have no power and things are malfunctioning due to the water ingestion.

Brent L.

That could create that much water

B That's not good

It seems we lost power on the boat. Because there is no power from the power cord.

So we had to hard wire it to gain power

Leeeeeee

Let fix the wires lol need boat lol

So seems we lost power snd with help of the rain the boat filled up some. And the waves and wind and the water caused further sinking

Leeeeeee

O got it

PLT-SUPPL-0043



